



Vehicle History Report™

US \$44.99

**2020 FORD
MUSTANG SHELBY COUPE**

VIN: 1FA6P8JZ8L5552666

COUPE

5.2L V8 V-Shaped

GASOLINE


REAR WHEEL DRIVE

Original Window Sticker

 **No accidents or damage reported to CARFAX**

 **Regular oil changes**

 **At least 1 open recall**

 **CARFAX 1-Owner vehicle**

 **Personal vehicle**

 **33,563 Last reported odometer reading**






This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/10/26 at 9:09:04 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
 Oil	 Oil and filter changed	04/03/2026
 Tires	 Tires rotated	04/03/2026



This car has been recently serviced. That's a good thing!



Additional History

Owner 1

Not all accidents / issues are reported to CARFAX

Total Loss

No total loss reported to CARFAX.



No Issues Reported

Structural Damage

No structural damage reported to CARFAX.



No Issues Reported

Airbag Deployment

No airbag deployment reported to CARFAX.



No Issues Reported

Odometer Check

No indication of an odometer rollback.



No Issues Indicated

Accident / Damage

No accidents or damage reported to CARFAX.



No Issues Reported

Manufacturer Recall

At least 1 manufacturer recall requires service. Locate an authorized Ford dealer or call 866-436-7332 to obtain more information about this recall.



Recall Reported

Basic Warranty

Original warranty estimated to have expired.



Warranty Expired



Title History

Owner 1

CARFAX guarantees the information in this section

Damage Brands

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon



Guaranteed

No Problem

Odometer Brands

Not Actual Mileage | Exceeds Mechanical Limits



Guaranteed

No Problem

GUARANTEED

– None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.

[View Terms](#) | [View Certificate](#)



Ownership History

The number of owners is estimated

Owner 1

Year purchased	2020
Type of owner	Personal
Estimated length of ownership	6 yrs. 4 mo.
Owned in the following states/provinces	Wisconsin
Estimated miles driven per year	5,596/yr
Last reported odometer reading	33,563



Detailed History

Owner 1

Purchased: 2020

Low mileage! This owner drove less than the industry average of 15,000 mi/yr

Personal Vehicle

5,596 mi/yr

Date	Mileage	Source	Comments
10/12/2019		FORD MOTOR COMPANY	Vehicle manufactured and shipped to original dealer - Original Window Sticker
10/26/2019	7	Lithia Ford of Racine Racine, WI 414-795-3433 lithiafordofracine.com/ ★ 4.2 / 5.0 329 Verified Reviews ♥ 5,057 Customer Favorites	Vehicle serviced - Pre-delivery inspection completed - Maintenance inspection completed - Battery/charging system checked - Brakes checked - Interior cleaned - Tire condition and pressure checked
04/23/2020	22	Wisconsin Motor Vehicle Dept. Fontana, WI	Odometer reading reported - Titled or registered as personal vehicle
07/16/2020		Wisconsin Motor Vehicle Dept. Fontana, WI	Title issued or updated - Registration issued or renewed - First owner reported - Vehicle color noted as Blue
08/05/2020		Ford Motor Company	⚠ Manufacturer Safety recall issued - NHTSA #20V263000 - Component: POWER TRAIN:AUTOMATIC TRANSMISSION:GEAR POSITION INDICATION (PRNDL) - Status: Remedy Available Description: Ford Motor Company (Ford) is recalling certain 2019 Expedition and 2019-2020 Mustang vehicles. The "Transmission Not In Park" warning message and associated chime duration are shorter than intended. Remedy: Ford will notify owners, and dealers will reprogram the instrument cluster, free of charge. The recall began May 26, 2020. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 20S21.

04/16/2021		Wisconsin Motor Vehicle Dept. Fontana, WI	Registration issued or renewed - Vehicle color noted as Pearl White
10/18/2021	8,125	Lithia Ford of Racine Racine, WI 414-795-3433 lithiafordofracine.com/ ★ 4.2 / 5.0 329 Verified Reviews ♥ 5,057 Customer Favorites	Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tires rotated
04/16/2022		Wisconsin Motor Vehicle Dept. Fontana, WI	Registration issued or renewed - Vehicle color noted as Magnetic Gray
02/04/2023	15,534	Lithia Ford of Racine Racine, WI 414-795-3433 lithiafordofracine.com/ ★ 4.2 / 5.0 329 Verified Reviews ♥ 5,057 Customer Favorites	Vehicle serviced - Maintenance inspection completed - Recommended maintenance performed - Alignment checked - Four tires balanced - Oil and filter changed - Tires rotated
04/16/2023		Wisconsin Motor Vehicle Dept. Fontana, WI	Registration issued or renewed - Vehicle color noted as Red
03/16/2024		Wisconsin Motor Vehicle Dept. Fontana, WI	Registration issued or renewed - Vehicle color noted as Oxford White
04/27/2024	22,537	Lithia Ford of Racine Racine, WI 414-795-3433 lithiafordofracine.com/ ★ 4.2 / 5.0 329 Verified Reviews ♥ 5,057 Customer Favorites	Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tires rotated
01/25/2025	26,798	Lithia Ford of Racine Racine, WI 414-795-3433 lithiafordofracine.com/ ★ 4.2 / 5.0 329 Verified Reviews ♥ 5,057 Customer Favorites	Vehicle serviced - Maintenance inspection completed - Brakes checked - Oil and filter changed - Tire(s) replaced - Tires rotated


03/16/2025

Wisconsin Motor Vehicle Dept.
Fontana, WI

Registration issued or renewed
- Vehicle color noted as Magnetic Gray

03/14/2026

Ford Motor Company


 **Manufacturer Safety recall issued**
- NHTSA #20V306000
- Component: FORWARD COLLISION
AVOIDANCE: SENSING SYSTEM: CAMERA
- Status: Remedy Available

Description: Ford Motor Company (Ford) is recalling certain 2020 Mustang vehicles equipped a forward-looking camera. The camera may be misaligned to the vehicle and features that are dependent on the camera such as Pre-Collision Assist, Adaptive Cruise Control, Lane Keeping System, Driver Alert, and Auto High Beam Control may not function as intended.

Remedy: Ford will notify owners, and dealers will perform the Lane Departure Warning System camera alignment procedure, free of charge. This recall began June 17, 2020. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 20S26.

03/14/2026

Ford Motor Company

 **Manufacturer Safety recall issued**
- NHTSA #20V573000
- Component: SERVICE BRAKES,
HYDRAULIC:PEDALS AND LINKAGES
- Status: Remedy Available

Description: Ford Motor Company (Ford) is recalling certain 2020 Mustang vehicles equipped with automatic transmissions. The brake pedal bracket may fracture during sudden stopping.

Remedy: Ford will notify owners, and dealers will replace the brake pedal bracket assembly, free of charge. The recall began January 26, 2021. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 20S52.

04/03/2026	33,563	Lithia Ford of Racine Racine, WI 414-795-3433 lithiafordofracine.com/ ★ 4.2 / 5.0 329 Verified Reviews ♥ 5,057 Customer Favorites	Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tires rotated
05/16/2026		Wisconsin Motor Vehicle Dept. Fontana, WI	Registration issued or renewed - Vehicle color noted as Pearl White



Glossary

CARFAX Well Maintained - Regular Oil Changes

CARFAX identifies a "Well Maintained - Regular Oil Change" vehicle as having a regular oil change history when all its recommended oil changes, based on the vehicle's maintenance schedule, have been reported to CARFAX. CARFAX uses the manufacturer's schedule and assumes normal driving conditions. When an oil change schedule is not available, CARFAX may analyze reported service events to determine what is typical for the same make and model vehicle. Dealers and service shops may publish different recommended service schedules.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Ford Recall

The Ford Motor Company provides CARFAX with Field Service Action and recall information regarding safety, compliance and emissions programs announced since 2000 for a specific vehicle. For complete information regarding programs or concerns about this vehicle, please contact a local Ford Dealer.

Manufacturer Recall

Automobile manufacturers issue recall notices to inform vehicle owners of a safety defect or failure to meet minimum federal safety or emissions standards. Manufacturer recalls are repaired at no cost to the customer.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.



Warranty Check™

CARFAX has estimated the remaining original manufacturer warranty coverage based on information reported to us on this **2020 FORD MUSTANG** (1FA6P8JZ8L5552666).

Please confirm remaining factory warranty and extended warranty options with your dealer or vehicle manufacturer.

2020 FORD MUSTANG

VIN:	1FA6P8JZ8L5552666
Estimated start date of warranty:	11/20/2020
Last CARFAX reading reported on 05/10/2026:	33,563 miles
Today's date:	05/10/2026

Type of Coverage	Original Warranty	Estimated Remaining Coverage
Basic	36 months or 36,000 miles	Coverage Expired
Drivetrain	60 months or 60,000 miles	Coverage Expired
Emissions	No data reported to CARFAX	
Corrosion	60 months or unlimited mileage	Coverage Expired
Transferable	No data reported to CARFAX	
Roadside	60 months or 60,000 miles	Coverage Expired
Safety belt & inflatable restraint	60 months or 60,000 miles	Coverage Expired
Specific Components	No data reported to CARFAX	

i CARFAX Warranty Check provides an **estimate** of this vehicle's remaining warranty coverage. It does not take into account some vehicle history events such as some title brands that may void the original manufacturer warranty or ownership transfers that may decrease warranty coverage. This warranty information is only valid for vehicles manufactured for the United States. Complete warranty coverage information is available for this vehicle at the Ford website.

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

SYSTEMATIC RETRIEVAL OF THE CONTENT OR OTHER DATA FROM THIS SITE TO CREATE OR COMPILE, DIRECTLY OR INDIRECTLY, IN WHOLE OR IN PART, A COLLECTION, COMPILATION, DATABASE OR DIRECTORY WITHOUT THE EXPRESS WRITTEN PERMISSION OF CARFAX IS STRICTLY PROHIBITED.

© 2026 CARFAX, Inc., part of S&P Global. All rights reserved.

5/10/2026, 9:09:04 PM (CST)